
DECORATION SPEC SHEET

CT106694 Carhartt® ANSI 107 Class 3 Waterproof Heavyweight Insulated Jacket





BACK DECORATION DIMENSIONS			
BA	Back	10" H x 10" W	Primary
BB	Back Bottom	4"HX14"W	

SLEEVE DECORATION DIMENSIONS			
LW	Left Wrist	4"HX4"W	
RW	Right Wrist	4"HX4"W	

HOOD DECORATION DIMENSIONS			
BH	Back Hood	3"HX3"W	
FH	Front Hood	3"HX3"W	
LHS	Left Hood Side	4"HX4"W	
RHS	Right Hood Side	4"HX4"W	

Decoration area is dependent on garment size, decoration method and the equipment being used. Please consult your decorator or supplier.

DECORATION TECHNIQUES

DECORATION SPEC SHEET

CT106694 Carhartt® ANSI 107 Class 3 Waterproof Heavyweight Insulated Jacket



PAD PRINTING




HEAT TRANSFER

ESSENTIAL PRODUCT INFORMATION

Due to the nature of 100% polyester fabrics, special care must be taken throughout the decoration process when heat is applied for curing. Please consult with your decorator or material supplier.

Due to the nature of water resistant coatings, special care must be taken throughout the decoration process. An ink catalyst additive or special adhesive heat transfer is required. Please consult with your decorator or material supplier.

TIPS FROM OUR EXPERTS BY DECORATION TECHNIQUE



PAD PRINTING
Pad printing uses a soft silicone pad to transfer an image taken from a plate etched with a reversed logo, similar to a rubber stamp. Images can be very small and detailed and can be up to 5½ inches in diameter. Pad printers are capable of printing up to six colors, however most industry printers use one to two colors at most when printing on apparel. Pad printing is a popular trend for tagless label printing. The prints are soft, durable and capable of high and low volume production. Pad printing is great for sling bags, totes and other items that are difficult to decorate, as well as styles that are heat sensitive.



HEAT TRANSFER
A graphic, name and or number applied to a textile with a heat press. Great for quantities of any size, sports name and numbering, fashion, performance wear, print on demand programs and on-site decorating events.

Heat transfers with an aggressive adhesive are required for stain release, water resistant/waterproof coated and nylon fabrics. Consult with your transfer supplier for recommendations.
Decoration is not recommended over reflective areas. Doing so may also violate OSHA requirements.

It is a best practice to consult with your decorator or consumable supplier(s) for accessories, specialty frames and applications that are specific to a shop's setup and equipment.